



PCTEL VCP Driver Product Release Notes

PCTEL VCP Driver Product Release Notes

Release 2.1.1.0

**Document Number: 14RN38-00M
Revision I**

May 2010

Restrictions: This document contains proprietary information that is protected by copyright; it is intended for use by PCTEL and its customers only. It is not to be disclosed to a third party. All rights reserved. No part of this document may be photocopied or reproduced in any way without the prior written permission of PCTEL RF Solutions Group. The information contained in this document is subject to change without notice. PCTEL RF Solutions Group makes no warranty of any kind with regard to this document. PCTEL RF Solutions Group shall not be liable for errors or omissions contained herein or for incidental or consequential damages in connection with the use of this document.



PCTEL VCP Driver Product Release Notes

COMMENT ON KNOWN DEFECTS AND OTHER ERRATA

This document lists problems known to be associated with the current release. PCTEL RF Solutions Group is committed to releasing defect free products, and appreciates any reports of issues or assistance in the identification of issues. Problems are prioritized and queued for remedy.

PCTEL RF Solutions Group is always interested in your feedback concerning our products, and the features or additions that would make them better. Please feel free to contact PCTEL RF Solutions Group using the support information below with any suggestions for improvements.

Trademarks

© 2010 PCTEL, Inc. All rights reserved. PCTEL®, SeeGull®, InSite®, CLARIFY®, the CLARIFY® logo and the PCTEL logo are registered trademarks of PCTEL, Inc. All other trademarks are property of their respective owners.

Notices and Warranty Information

The information in this document is subject to change without notice and should not be construed as commitment by PCTEL. PCTEL assumes no responsibility or makes no warranties for any errors that may appear in this document and disclaims any implied warranty of merchantability or fitness for a particular purpose.

Copyright Information

No part of this document may be used or copied in any form or any means without prior written consent of PCTEL.

All Rights Reserved

Copyright 1997-2010

PCTEL, Inc.
RF Solutions Group
20410 Observation Drive, Suite 200
Germantown, MD 20876 USA
Phone: +1 301 515 0036
Fax: +1 301 515 0037



PCTEL VCP Driver Product Release Notes

Table of Contents

1.0	Current Release Notes.....	4
2.0	Previous Release Notes.....	5
2.1	Release 2.0.1.0 (April 2009).....	5
2.2	Release 2.0.0.46 (December 2008).....	6



1.0 Current Release Notes

COMPONENT VERSION INFORMATION

Component Name	Version
PCTEL VCP Driver MSI file	2.1.1.0
PCTEL VCP Driver	2.1.0.56

FEATURES

- Support Windows 7 32/64 bit, and Windows Vista 64 bit

SUPPORTED OPERATING SYSTEMS

- Windows XP 32 bit, U.S. version only, Service Pack 3
- Windows Vista 32/64 bit Business Edition, U.S. version only
- Windows 7 32/64 bit Ultimate Edition, U.S. version only

KNOWN PROBLEMS IDENTIFIED IN THIS RELEASE

None

PROBLEMS RESOLVED IN THIS RELEASE

None



2.0 Previous Release Notes

2.1 Release 2.0.1.0 (April 2009)

COMPONENT VERSION INFORMATION

Component Name	Version
PCTEL VCP Driver MSI file	2.0.1.0
PCTEL VCP Driver	2.0.0.46

FEATURES

- None. (Defect Fixes only)

SUPPORTED OPERATING SYSTEMS

- Windows XP Profession Edition SP2, U.S. version only
- Windows Vista Business Edition SP1, U.S. version only

KNOWN PROBLEMS IDENTIFIED IN THIS RELEASE

None.

PROBLEMS RESOLVED IN THIS RELEASE

- If the computer required a system reboot after installing the PCTEL VCP driver, the installation process treated the system reboot as a fail installation and, as a result, the installation process is “rolled back”. The end result is the driver is not installed in all scenarios.



PCTEL VCP Driver Product Release Notes

2.2 Release 2.0.0.46 (December 2008)

COMPONENT VERSION INFORMATION

Component Name	Version
PCTEL VCP Driver	2.0.0.46

FEATURES

- Supported Vista Business edition operating system
- Obtained Microsoft WHQL certification for XP and Vista
- MSI installation package is created
- Automatic cleanup procedure for VCP driver of previous versions is included